UST Facility I.D.( (FID) # 5063				
	Contact Number			
Facility Name	Contact email			
Address 51451 State Road 19, SIKhart	Date of Inspection	1/28/25		
Duty Name	Name of the Person Conducting Inspection	ANSMIT		
Operator Training current Ope	Or Trainin	OperatorNotified	Qea	0
Is Registration current with correct owner, operator etc. (	On/Notification Form Nies Olio	OperatorNotified	Qes	Q
×	elease Detection		77	Other
Make and Model	くれている	(	(	) (
Does it have paper?	Qies Qies	OperatorNotified	Qres	(F
Is it in Alarm mode?		OperatorNotfied	Ckes	
Interstitial Monitoring Sensor Status Normal		OperatorNotified		X 5' 8'
INCRESSERY INTOLLERBY FILLIOUT TENERS	Spill Buckets	- Cycle and a second		(
Are Spill Buckets Clean and free from water, debris, product etc?  Are the Spill Bucket in good condition and free of damage/cracks	NN	OperatorNotified OperatorNotified	(g) (g)	
Is Fill pipe cap tight and fill pipe free from any obstruction?		OperatorNotified	Qes .	Qi <sub>o</sub>
Are Sumps Clean and free from water, debris, product etc? Pipin	Mes Sumps	OperatorNotified	O les	0
Are UDCs clean and free from water, debris, product etc? (	Ser Containments (UDC)  Wes	OperatorNotified	) es	) (
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOS FOLLOWING PROPER PROCE	SED OFF ACCORDING	60	000	SNOILY
Operator on Duty Name	Signature		Date	
317-645-0215 tanksd	tanksdata@gmail.com		www.tanksda	t/a_com

A PROPERTY OF THE PARTY OF THE