	20	DAVEWA	LK THROUGH	INSPEC	TION		
	3(DAIS	ALIAN LALACO				
Tanks Data	Contact Nu	Contact Number					
UST Facility I.D.((FID) # 9258		Contact email					
Facility Name 77760	Data of Incr	Date of Inspection () 7 - 06 - 2025					
Address 6/0/ Bradway 46410	LABORATOR						
Operator on Duty Name	Conducting	Inspection	rurpreet				
C	perator Train	ing		_	No		
Operator Training current	Yes	No	OperatorNotified	OY'es	0,0		
Registr	ation/Notificat		OperatorNotified	Ores	No		
Is Registration current with correct owner, operator etc.	Yes	ÛN ₀	OperatorNothicu	O			
	Release Detecti	OIM	()BIR	OIC	Other		
Release Detection Method	COATG	, CIM	Osm				
Make and Model / R 165	750 Fr	Ova	OperatorNotified	Yes	Olo		
Does it have paper?	Yes	QNo V	OperatorNotified	Yes	No		
Is it in Alarm mode?	Yes	QN ₀	[[[[라이크리 [[[[[[[[[[[[[[[[[[[\times	K		
Interstitial Monitoring Sensor Status Normal	Yes	QNo	OperatorNotified	Yes	X		
Necessary Monthly Printout Taken	Yes	ONO	OperatorNotified	Ores	O _{No}		
	Spill Bucket	s		10	0.		
Are Spill Buckets Clean and free from water, debris, product etc	? Xes	(No	OperatorNotified	Ces	N°		
Are the Spill Bucket in good condition and free of damage/crack	s Ores	ONo	OperatorNotified	Oes	Olo		
	Fill Ports	~		_	0		
Is Fill pipe cap tight and fill pipe free from any obstruction?	(Yes	ON0	OperatorNotified	Oes	O40		
	Piping/STP Su		0	8	Ois		
Are Sumps Clean and free from water, debris, product etc?	Yes	(V)O	OperatorNotified	Ves	Oyo		
	penser Contain			0	0		
Are UDCs clean and free from water, debris, product etc?	Yes	(No	OperatorNotified		O10		
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS FOLLOWING PROPER PR	SPOSSED OFF ROCEDUE BY A	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU			
Operator on Duty Name		Signature	2	Date	7-06-	50	
[[대] [[대] [[대] [[대] [[대] [[대] [[대] [[대]	ksdata@gmail.c	om	2	www.tank	sdata.com		
V.,						20222416	