

Work Order: 413132

Status: Invoiced

Date:

3/19/2025

Location: SO. BEND BP EXPRESS

Bill To: SO. BEND BP EXPRESS

**Lucky Ghotra
5307 WESTERN
SOUTH BEND, IN 46619**

**5307 WESTERN
SOUTH BEND, IN 46619**

Solution Notes

[Issue:] needs quote request for failed spill containers
Lucky h 3/19/25

Filled out a quote request for the premium spill container and drop tube. Filled out quote request to replace the missing diesel drop tube. Filled out quote request for the stuck regular drop tube. Attempted to remove the ball floats on both regular and premium tanks. None of the ball float could be removed. Confirmed the tank monitor has the correct size for the diesel tank.

Subtotal:

SC/ST:

Total: