

----- SYSTEM ALARM -----
PRINTER ERROR
OCT 1, 2024 12:41 PM

STAR STOP
HWY 50
BEDFORD.IN

OCT 1, 2024 1:31 PM

CSLD TEST RESULTS

OCT 1, 2024 1:31 PM

T 1:UNLEADED
PROBE SERIAL NUM 183505

0.2 GAL/HR TEST
PER: OCT 1, 2024 FAIL

T 2:PREMIUM
PROBE SERIAL NUM 823606

0.2 GAL/HR TEST
PER: OCT 1, 2024 PASS

T 3:DIESEL
PROBE SERIAL NUM 213017

0.2 GAL/HR TEST
PER: OCT 1, 2024 PASS

* * * * * END * * * * *

STAR STOP
HWY 50
BEDFORD, IN

OCT 1, 2024 1:31 PM

LEAK TEST REPORT

T 1: UNLEADED
PROBE SERIAL NUM 183505

NO TEST DATA AVAILABLE

* * * * * END * * * * *

STAR STOP
HWY 50
BEDFORD, IN

OCT 1, 2024 1:31 PM

LEAK TEST REPORT

T 2: PREMIUM
PROBE SERIAL NUM 823606

NO TEST DATA AVAILABLE

* * * * * END * * * * *

STAR STOP
HWY 50
BEDFORD, IN

OCT 1, 2024 1:31 PM

LEAK TEST REPORT

T 3: DIESEL
PROBE SERIAL NUM 213017

NO TEST DATA AVAILABLE

* * * * * END * * * * *

