

 Midwest Tank Testing AN ENVIRONMENTAL COMPLIANCE COMPANY 316 W Indiana Ave Chesterton, IN 46304		HYDROSTATIC SPILL BUCKET		DATE AND TIME		9-27-21 8:15-12:15	
		(HSB) INTEGRITY TEST		WEATHER		85 Sunny	
		DATA SHEET		COLLECT/INVOICE		Collect	
				CLIENT E-MAIL		luckyghotra95@ymail.com	
Test Location Information				Testing Company Information			
PC # and WO #				Name		Midwest Tank Testing	
Name and FID #		Marathon FID# 24742		Address		316 W Indiana Ave.	
Address		3204 Monroe St		City/State/Zip		Chesterton, IN 46304	
City/State/Zip		LaPorte IN 46350		Phone		800-975-1436	
Contact		Lucky		Technician Information			
Phone		219-369-6944		Name		Jason Muller	
				Cert #		68-4891	
HYDROSTATIC SPILL BUCKET (HSB) INTEGRITY TEST							
This procedure is to test the leak integrity of single and double walled spill buckets. See PEI/RP1200 Section 6.2 for hydrostatic test method.							
Tank #	1	2					
Product Stored	Regular	Premium					
Manufacturer							
Construction (Single Wall/Double Wall)	Single	Single					
Test Type (Single Wall/Double Wall)	HYDROST. SINGLE WALL	HYDROST. SINGLE WALL					
Spill Bucket Type (Product/Vapor)	Product	Product					
Liquid and Debris Removed From Spill Bucket? (All liquids & debris must be disposed of properly) (Yes/No)	Yes	Yes					
Visual Inspection (No cracks, loose parts or separation of bucket from the fill pipe) If fail, omit hydrostatic test. (Pass/Fail)	Pass	Pass					
Tank Riser Cap Included In Test? (Yes, No, N/A)	Yes	Yes					
Drain Valve Included In Test? (Yes, No, N/A)	Yes	Yes					
Starting Water Level (inches)	8	7					
Test Start Time	9:15 AM	9:15 AM					
Ending Water Level (inches)	7	5					
Test End Time	10:15 AM	10:15 AM					
Test Period (minutes)	60	60					
Water Level Change (inches)	1	2					
Pass/Fail Criteria: Must pass visual inspection. Hydrostatic: Water level drop of less than 1/8"							
Test Results (Pass/Fail)	Fail	Fail					
Comments: Spill buckets are metal and considerably corroded. Adapters might need to be changed out for new ones.							