

HYDROSTATIC SPILL BUCKET (HSB) INTEGRITY TEST DATA SHEET

DATE AND TIME	11/16/22 - 12:00 PM
WEATHER	35 Snowy
COLLECT/INVOICE	Collected
CLIENT E-MAIL	

Testing Company Information

Test Location Information Certi		Certifications	Name	Midwest Tank Testing		
PC # and WO #		Estabrooks: 82-1906	Address	316 W. Indiana Ave.		
Name and FID #	Amoco - FID 16625	ICC: 10221928	City/State/Zip	Chesterton, IN 46304		
Address	8498 S. US Hwy 6	Indiana: UC 110386	Phone	800-975-1436		
City/State/Zip	Kingsford Heights, IN 46532	CP/STI: 16655	Technician Information			
Contact			Name	Chris Zell		
Phone			Email	support@midwesttanktesting.com		

HYDROSTATIC SPILL BUCKET (HSB) INTEGRITY TEST

This procedure is to test the leak integrity of single and double walled spill buckets. See PEI/RP1200 Section 6.2 for hydrostatic test method.

Tank #	1	2					
Product Stored	Regular	Premium					
Manufacturer	-						
Construction (Single Wall/Double Wall)	Single	Single					
Test Type (Single Wall/Double Wall)	HYDROST. SINGLE WALL	HYDROST. SINGLE WALL					
Spill Bucket Type (Product/Vapor)	Product	Product					
Liquid and Debris Removed From Spill Bucket? (All liquids & debris must be disposed of properly) (Yes/No)	Yes	Yes					
Visual Inspection (No cracks, loose parts or separation of bucket from the fill pipe) If fail, omit hydrostatic test. (Pass/Fail)	Pass	Pass					
Tank Riser Cap Included In Test? (Yes, No, N/A)	Yes	Yes					
Drain Valve Included In Test? (Yes, No, N/A)	Yes	Yes					
Starting Water Level (inches)	12	12					
Test Start Time	12:30 PM	12:30 PM					
Ending Water Level (inches)	12	12					
Test End Time	1:30 PM	1:30 PM					
Test Period (minutes)	60	60					
Water Level Change (inches)	0	0					
Pass/Fail Criteria: Must pass visual inspec	ction. Hydro	static: Wate	er level drop	of less tha	n 1/8"	•	•
Test Results (Pass/Fail)	Pass	Pass					

Comments: