



AN ENVIRONMENTAL COMPLIANCE COMPANY
316 W. Indiana Ave.
Chesterton, IN 46304

EZY CHEK SYSTEMS

PRODUCT LINE TEST

DATE AND TIME

1/17/2023 - 9:20 AM

Test Location Information

PC # and WO #	
Name and FID #	Phillips 66 - FID 16239
Address	613 Pine Lake Ave
City/State/Zip	LaPorte, IN 46351
Contact	
Phone	

Testing Company Information

Name	Midwest Tank Testing
Address	316 W. Indiana Ave.
City/State/Zip	Chesterton, IN 46304
Phone	800-975-1436

Technician Information

Name	Chris Zell
Email	support@midwesttanktesting.com
Applied Pressure	1-1/2 Times Working Pressure, Min 50 PSI

PRODUCT LINE TEST - DATA (LT)

#1	Product Type:		Regular			
TIME	DATA	-/+	GPL	RES	GPH	
9:45	90	0	0.0037	0.0000	0.0000	
10:00	83	-7	0.0037	-0.0259	-0.1036	
10:15	81	-2	0.0037	-0.0074	-0.0296	
10:30	79	-2	0.0037	-0.0074	-0.0296	
10:45	77	-2	0.0037	-0.0074	-0.0296	
11:00	75	-2	0.0037	-0.0074	-0.0296	
FINAL RESULT:						
			Pass			

#2	Product Type:		Mid			
TIME	DATA	-/+	GPL	RES	GPH	
9:45	90	0	0.0037	0.0000	0.0000	
10:00	88	-2	0.0037	-0.0074	-0.0296	
10:15	86	-2	0.0037	-0.0074	-0.0296	
10:30	84	-2	0.0037	-0.0074	-0.0296	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
FINAL RESULT:						
			Pass			

#3	Product Type:		Premium			
TIME	DATA	-/+	GPL	RES	GPH	
9:45	90	0	0.0037	0.0000	0.0000	
10:00	88	-2	0.0037	-0.0074	-0.0296	
10:15	86	-2	0.0037	-0.0074	-0.0296	
10:30	84	-2	0.0037	-0.0074	-0.0296	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
FINAL RESULT:						
			Pass			

#4	Product Type:					
TIME	DATA	-/+	GPL	RES	GPH	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
FINAL RESULT:						

#5	Product Type:					
TIME	DATA	-/+	GPL	RES	GPH	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
FINAL RESULT:						

#6	Product Type:					
TIME	DATA	-/+	GPL	RES	GPH	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
		0	0.0037	0.0000	0.0000	
FINAL RESULT:						

COMMENTS/RECOMMENDATIONS: I used the shut off valve for regular, then I used the bullet, then I had to use the shear valves. After shutting the shear valves pressure began holding. Regular shut off valve needs repaired.