

Service Report

Work Order: 420526

Status: Exception Date: 10/28/2025

Location: PHILLIPS 66 -SOUTH BEND Bill To: PHILLIPS 66 -SOUTH BEND

Lucky Ghotra

4005 W WESTERN AVE4005 W WESTERN AVESOUTH BEND, IN 46619SOUTH BEND, IN 46619

Solution Notes

[Issue:] dan 10/28/2025. Hydrotest both stps, clean out spill containers, and plug off secondary's o Dan 10/28/2025. Hydrotested all sumps and and cleaned out spill containers. Plugged off tubing for secondary at last dispenser. Filled out hydrotesting form for both stps and also udcs.