

Work Order: 416343

Status: Invoiced

Date:

6/25/2025

Location: HANDY SPOT MARATHON

Bill To: HANDY SPOT MARATHON

**Baljinder Singh
2701 PRAIRIE STREET
ELKHART, IN 46517**

**2701 PRAIRIE STREET
ELKHART, IN 46517**

Solution Notes

[Issue:]Dsl probe cable stuck

Mark H. 6/25/25

Removed dsl probe cable from probe head and tested probe. Filled out paperwork for the state.

[Issue:]Stp sumps have liquid in them

Mark H. 6/25/25

Investigated sumps and found no gravel in them. Sumps had liquid in them. Liquid looked old. Informed owner he needed to get sumps sucked out and monitor to see if more water came in. Site does not have a water table.
