

PETROLEUM TESTING SERVICES, LLC  
PO BOX 146  
YORKTOWN, IN 47396  
765-749-5540  
EMAIL:petroleumtesting@aol.com

SITE: MOBIL  
ADDRESS: 750 CR 15  
CITY,ST,ZIP: ELKHART, IN 46516

FID 15500

DATE: 2/7/2023

## ATG FUNCTIONALITY

### ATG MAKE AND MODEL

TANK NUMBER

PRODUCT

TANK VOLUME

TANK DIAMETER

TANK PROBE HAS NO DAMAGED PARTS?

DAMAGED OR MISSING PARTS REPLACED?

FLOATS MOVE FREELY ON STEM?

FUEL FLOAT AGREES W/ CONSOLE?

INCH LEVEL WATER FLOAT ACTIVATES ALARM?

WATER FLOAT AGREES W/ CONSOLE?

INCH LEVEL OVERFILL ACTIVATES ALARM?

OVERFILL ALARM AGREES W/ CONSOLE?

ALL SENSORS LABELED CORRECTLY?

STP/UDC SENSORS ACTIVATE ALARM?

INTERSTITIAL TANK SENSORS ACTIVATE ALARM?

.2 MONTHLY MONITORING ACTIVE?

BATTERY BACKUP IS FUNCTIONAL?

RESULT

COMMENTS:

UNL & DSL STP ALARM ACTIVATED ON ARRIVAL. DSL CLEARED. UNLEAD COULD NOT BE CLEARED.

VR450

| 1     | 2    | 3    | 4    | 5 |
|-------|------|------|------|---|
| UNL   | PREM | DSL  | KERO |   |
| 19782 | 6321 | 6044 | 3765 |   |
| 119   | 119  | 91   | 91   |   |
| N     | N    | N    | N    |   |
| NA    | NA   | NA   | NA   |   |
| Y     | Y    | Y    | Y    |   |
| Y     | Y    | Y    | Y    |   |
| 1     | 1    | 1    | 1    |   |
| Y     | Y    | Y    | Y    |   |
| 119   | 119  | 91   | 91   |   |
| Y     | Y    | Y    | Y    |   |
| Y     | Y    | Y    | Y    |   |
| Y     | Y    | Y    | Y    |   |
| Y     | Y    | Y    | Y    |   |
| Y     | Y    | Y    | Y    |   |
| YES   |      |      |      |   |
| FAIL  | PASS | PASS | PASS |   |

TECHNICIAN: RONNIE BROWN

CERTIFICATION:

UC2017IN12086