

Work Order: 413141

Status: Invoiced

Date:

3/27/2025

Location: SR 23 PROPERTY, LLC

Bill To: AMOCO

**Lucky Ghotra
59572 MAYFLOWER ROAD
SOUTH BEND, IN 46614**

**59572 MAYFLOWER ROAD
SOUTH BEND, IN 46614**

Problem Notes

03/13/2025 14:07 BEN OLTHOFF

- HSC/HDC Fail (PREM STP, DSL STP, DISP1/2, DISP 7/8)
 - Failed hydro testing under 2 STPs & 2 UDCs

Solution Notes

[Issue:] check leaking sump

Luke h 3/20/25

Found no major issues tightened down loose opw boots. Someone needs to return and hydrdo test these four sumps.

[Issue:] sumps need testing

Luke h 3/27/25

Tightened all entry boots on sumps. Tested udc 1/2, 7/8 and diesel, premium stps. All sumps passed.
