

Work Order: 413676

Status: Invoiced

Date:

4/3/2025

Location: QUICK MART

Bill To: QUICK MART

**Raj Singh
1606 CASSOPOLIS STREET
ELKHART, IN 46514**

**1606 CASSOPOLIS STREET
ELKHART, IN 46514**

Problem Notes

04/01/2025 11:10 BEN OLTHOFF

Raj approved a t&m service call to investigate the following failures:

- Overfill Prevention (FAIL-ALL)
 - Tester said adapters are in rough shape and did not attempt to remove. Cut adapters if need be and test the ball floats. Fill out relevant quote request if needed.
- Hydrostatic Spill Bucket (Premium-Fail)
 - PUL bucket failed a hydro test. Fill out quote request to replace

Test results in Attachments

Solution Notes

[Issue:]test ball floats
Jack. 4/3/25.

All ball floats failed due to tester not wanting to attempt to get vapor adapters off. Had to cut off vapor adapters for diesel, premium and regular and replaced. Kerosene adapter came off. Premium ball float tested good. Attempted to get ball floats out of the diesel, regular and kerosene riser and the bar broke on all the ball floats. Need to return with proper extractor to get ball floats out. Made quote request for drop tubes on those three tanks.

[Issue:]premium spill bucket
Made quote request for premium spill bucket due to it failing a hydrostatic test.
