



5296 Breakers Way, Carmel, IN 46033

www.tanksdata.com
tanksdata@gmail.com
(317)-300-6065

Date 3/4/24

HYDROSTATIC SPILL BUCKET INTEGRITY TEST

SINGLE- AND DOUBLE-WALLED VACUUM TEST METHOD

Facility Name:	Shell	Owner:	Tristar Holdings Inc
Address:	1401 E 29 St	Address:	13280 Talbott Dr
City, State, Zip Code:	Muncie, IN 47302	City, State, Zip Code:	Fishers, IN 46037
Facility I.D. #:	2255	Phone #:	

This procedure is to test the leak integrity of single- and double-walled spill buckets. See PEI/RPI200 Section 6.2 for hydrostatic test method, Section 6.3 for single-walled vacuum test method and Section 6.4 for double-walled vacuum test method.

Tank Number	1	2	3	4	5	
Product Stored	Regular	Regular	Premium	Diesel	Diesel	
Spill Bucket Capacity	5 gal	5 gal	5 gal	5 gal	5 gal	
Manufacturer	Opw	Opw	Opw	Opw	Opw	
Construction	SW	SW	SW	SW	SW	
Test Type	Hydrostatic	Hydrostatic	Hydrostatic	Hydrostatic	Hydrostatic	
Spill Bucket Type	Product	Product	Product	Product	Product	
Liquid and debris removed from spill bucket?	No	No	No	No	No	
Visual Inspection (No cracks, loose parts or separation of the bucket from the fill pipe.)	Pass	Pass	Pass	Fail	Fail	
Tank riser cap included in test?	Yes	Yes	Yes			
Drain valve included in test?	No	No	No			
Starting Level	11.25 in	10.75 in	11.25 in	N/a	N/a	
Test Start Time	10:15	10:15	10:15			
Ending Level	10 in	10.75 in	11.25 in			
Test End Time	11:25	11:25	11:25			
Test Period	1hr	1hr	1hr			
Level Change	1.25 inch	No	No			
Pass/fail criteria: Must pass visual inspection. Hydrostatic: Water level drop of less than 1/8 inch; Vacuum single-walled only: Maintain at least 26 inches water column; Vacuum double-walled: maintain at least 12 inches water column						
Test Results	Fail	Pass	Pass	Fail	Fail	

Comments:

Tester's Name : Austin Fisher Tester's Signature : Austin Fisher