



5296 Breakers Way, Carmel, IN 46033

www.tanksdata.com
tanksdata@gmail.com
(317)-300-6065

Date 10/22/24

HYDROSTATIC SPILL BUCKET INTEGRITY TEST

SINGLE- AND DOUBLE-WALLED VACUUM TEST METHOD

Facility Name:	Citgo	Owner:	R&A Olive Property LLC
Address:	421 N Olive St	Address:	51324 COLLEEN CT
City, State, Zip Code:	South Bend, IN 46628	City, State, Zip Code:	Granger, IN, 46530
Facility I.D. #:	14296	Phone #:	

This procedure is to test the leak integrity of single- and double-walled spill buckets. See PEI/RP1200 Section 6.2 for hydrostatic test method, Section 6.3 for single-walled vacuum test method and Section 6.4 for double-walled vacuum test method.

Tank Number	1	2				
Product Stored	Regular	Premium				
Spill Bucket Capacity	3-4 gal	3-4 gal				
Manufacturer	EBW	EBW				
Construction	SW	SW				
Test Type	Hydrostatic	Hydrostatic				
Spill Bucket Type	Product	Product				
Liquid and debris removed from spill bucket?	Yes	Yes				
Visual Inspection (No cracks, loose parts or separation of the bucket from the fill pipe.)	Pass	Pass				
Tank riser cap included in test?	Yes	Yes				
Drain valve included in test?	Yes	Yes				
Starting Level	9"	9"				
Test Start Time	1:15pm	1:30pm				
Ending Level	9"	5"				
Test End Time	2:15pm	2:30pm				
Test Period	1 Hr	1 Hr				
Level Change	0	-4"				

Pass/fail criteria: Must pass visual inspection. Hydrostatic: Water level drop of less than 1/8 inch; Vacuum single-walled only: Maintain at least 26 inches water column; Vacuum double-walled: maintain at least 12 inches water column

Test Results	Pass	Fail				
--------------	------	------	--	--	--	--

Comments: Spillbuckets are older, more shallow but wide style and not 10.5" + deep.

Tester's Name : Josh Rider

Tester's Signature :