

5296 Breakers Way, Carmel, IN 46033

	www.tanksdata.com
\bowtie	tanksdata@gmail.com
	(317)-300-6065

Date

9/9/25

HYDROSTATIC SPILL BUCKET INTEGRITY TEST

SINGLE- AND DOUBLE-WALLED VACUUM TEST METHOD

Facility Name: Mara			Owner: Ms I						
Address: 2754 E 100 S				Address: 2754 E 100 S					
City, State, Zip Code: Anderson	, IN 46017			City, State, Zip Code:		Anderson, IN 46017			
Facility I.D. #: 10	361			Phone #:					
This procedure is to test the leak integrity of single- and double-walled spill buckets. See PEI/RP1200 Section 6.2 for hydrostatic test method, Section 6.3 for single-walled vacuum test method and Section 6.4 for double-walled vacuum test method.									
Tank Number	1								
Product Stored	Regular								
Spill Bucket Capacity	5 Gal								
Manufacturer	EMCO								
Construction	sw	•	•			•			
Test Type	Hydrostati		•						
Spill Bucket Type	Product	•	•						
Liquid and debris removed from spill bucket?	Yes	•							
Visual Inspection (No cracks, loose parts or separation of the bucket from the fill pipe.)	Pass	•							
Tank riser cap included in test?	Yes								
Drain valve included in test?	No	lacksquare							
Starting Level	11.5"								
Test Start Time	11:30 am								
Ending Level	11.5"								
Test End Time	12:30 pm								
Test Period	1hr								
Level Change	0								
Pass/fail criteria: Must pass visual inspection. Hydrostatic: Water level drop of less than 1/8 inch; Vacuum single-walled only: Maintain at least 26 inches water column; Vacuum double-walled: maintain at least 12 inches water column									
Test Results	Pass	•							
New Spill Bucket Installed for REG Comments:									
Tester's Name : Virender Kumar Tester's Signature :									