

Service Report

Work Order: 415443

Status: Invoiced Date: 6/4/2025

Location: CITGO Bill To: CITGO

Prince Ghotra

4575 W 37TH AVENUE 4575 W 37TH AVENUE HOBART, IN 46342 HOBART, IN 46342

Solution Notes

[Issue:] stp flex's need isolation sleeves Luke h 6/4/25

Dug out fill around the regular and premier stp motors. Installed isolation sleeves around the product flex.

Subtotal:

SC/ST:

Total: