



5296 Breakers Way, Carmel, IN 46033

www.tanksdata.com
tanksdata@gmail.com
(317)-300-6065

Date 3/26/25

HYDROSTATIC SPILL BUCKET INTEGRITY TEST

SINGLE- AND DOUBLE-WALLED VACUUM TEST METHOD

Facility Name:	Quik Mart Citgo
Address:	800 West 61st Ave
City, State, Zip Code:	Merrillville, IN 46410
Facility I.D. #:	15886

Owner:	PRINCE LLC
Address:	800 WEST 61ST AVE
City, State, Zip Code:	Merrillville, IN 46410
Phone #:	

This procedure is to test the leak integrity of single- and double-walled spill buckets. See PEI/RPI200 Section 6.2 for hydrostatic test method, Section 6.3 for single-walled vacuum test method and Section 6.4 for double-walled vacuum test method.

Tank Number	1	2				
Product Stored	Regular	Premium				
Spill Bucket Capacity	5 gal	5 gal				
Manufacturer	OPW	OPW				
Construction	SW	SW				
Test Type	Hydrostatic	Hydrostatic				
Spill Bucket Type	Product	Product				
Liquid and debris removed from spill bucket?	Yes	Yes				
Visual Inspection (No cracks, loose parts or separation of the bucket from the fill pipe.)	Fail	Fail				
Tank riser cap included in test?						
Drain valve included in test?						
Starting Level						
Test Start Time						
Ending Level						
Test End Time						
Test Period	1 Hr	1 Hr				
Level Change						

Pass/fail criteria: Must pass visual inspection. Hydrostatic: Water level drop of less than 1/8 inch; Vacuum single-walled only: Maintain at least 26 inches water column; Vacuum double-walled: maintain at least 12 inches water column

Test Results	Fail	Fail				
--------------	------	------	--	--	--	--

Comments: Both snapcaps are broken and will not seal tightly. Test will not pass with these snapcaps. Need replaced.

Tester's Name : Josh Rider

Tester's Signature :