

STAR STOP
HWY 50
BEDFORD,IN

OCT 24, 2023 2:52 PM

LEAK TEST REPORT

T 1:UNLEADED
PROBE SERIAL NUM 183505

NO TEST DATA AVAILABLE

***** END *****

STAR STOP
HWY 50
BEDFORD,IN

OCT 24, 2023 2:52 PM

LEAK TEST REPORT

T 2:PREMIUM
PROBE SERIAL NUM 823006

NO TEST DATA AVAILABLE

***** END *****

STAR STOP
HWY 50
BEDFORD,IN

OCT 24, 2023 2:52 PM

LEAK TEST REPORT

T 3:DIESEL
PROBE SERIAL NUM 213017

NO TEST DATA AVAILABLE

***** END *****

STAR STOP
HWY 50
BEDFORD,IN

OCT 24, 2023 2:52 PM