

STAR STOP  
HWY 50  
BEDFORD.IN

DEC 10, 2024 2:53 PM

OSLD TEST RESULTS

DEC 10, 2024 2:53 PM

T 1:UNLEADED  
PROBE SERIAL NUM 183505

0.2 GAL/HR TEST  
PER: DEC 10, 2024 PASS

T 2:PREMIUM  
PROBE SERIAL NUM 823606

0.2 GAL/HR TEST  
PER: DEC 10, 2024 PASS

T 3:DIESEL  
PROBE SERIAL NUM 213017

0.2 GAL/HR TEST  
PER: DEC 10, 2024 PASS

\* \* \* \* \* END \* \* \* \* \*

STAR STOP  
HWY 50  
BEDFORD.IN

DEC 10, 2024 2:53 PM

LEAK TEST REPORT

T 1:UNLEADED  
PROBE SERIAL NUM 183505

NO TEST DATA AVAILABLE

\* \* \* \* \* END \* \* \* \* \*

STAR STOP  
HWY 50  
BEDFORD.IN

DEC 10, 2024 2:53 PM

LEAK TEST REPORT

T 2:PREMIUM  
PROBE SERIAL NUM 823606

NO TEST DATA AVAILABLE

\* \* \* \* \* END \* \* \* \* \*

STAR STOP  
HWY 50  
BEDFORD.IN

DEC 10, 2024 2:53 PM

LEAK TEST REPORT

T 3:DIESEL  
PROBE SERIAL NUM 213017

NO TEST DATA AVAILABLE

\* \* \* \* \* END \* \* \* \* \*