

UST OVERFILL EQUIPMENT INSPECTION AUTOMATIC SHUTOFF DEVICE AND BALL FLOAT VALVE

Facility Name:	Marathon	Owner:	
Address:	2754 E 100 S	Address:	
City, State, Zip Code:	Anderson, IN 46017	City, State, Zip Code:	
Facility I.D. #:	10361	Phone #:	

This data sheet is for inspecting automatic shutoff devices and ball float valves. See PEI/RP1200 Section 7 for inspection procedures.

Product Grade	Regular	Premium	Diesel			
Tank Number	1	2	3			
Tank Volume, gallons	10,000	6,000	6,000			
Tank Diameter, inches	96	96	96			
Overfill Prevention Device Brand	OPW	OPW	OPW			
Type of Overfill Device	ASD	ASD	ASD			

AUTOMATIC SHUTOFF DEVICE INSPECTION

1. Drop tube removed from tank?	No	No	Yes			
2. Drop tube and float mechanisms free of debris?			Yes			
3. Float moves freely without binding and poppet moves into flow path?			Yes			
4. Bypass valve in the drop tube open and free of blockage (if present)?			Yes			
5. Flapper adjusted to shut off flow at 95% capacity?*			Yes			
6. Is Ball Float Present?						
7. Measured Auto Shut-Off Level						

A "No" to any item in Lines 1-5 indicates a test failure.

BALL FLOAT VALVE INSPECTION

1. Tank top fittings vapor- tight and leak-free?						
2. Ball float cage free of debris?						
3. Ball free of holes and cracks and moves freely in cage?						
4. Vent hole in pipe open and near top of tank?						
5. Ball float pipe proper length to restrict flow at 90% capacity?*						
6. Ball Float removed from the tank?						
7. Ball Float Level						

A "No" to any item in Lines 1-5 indicates a test failure.

Test Results	Fail	Fail	Pass			
--------------	------	------	------	--	--	--

Comment: Regular and premium adaptors are rusted onto riser and will not come out of the ground.

* Use manufacturer's suggested procedure for determining if automatic shutoff device will shut off flow at 95% capacity.

** Use manufacturer's suggested procedure for determining if flow restriction device will restrict flow at 90% capacity.

Tester's Name : Josh Rider

Tester's Signature : 