

5296 Breakers Way, Carmel, IN 46033

(III)	www.tanksdata.com
\boxtimes	tanksdata@gmail.com
3	(317)-300-6065

Date

5/6/25

HYDROSTATIC SPILL BUCKET INTEGRITY TEST SINGLE- AND DOUBLE-WALLED VACUUM TEST METHOD

Facility Name: Quik Mart Citgo					Owner: Meet, Inc.							
Address: 4700 Broadway					Address:	Address: 4700 Broadway						
City, State, Zip Code: Gary, IN 46408				İ	City, State, Zip Code: Gary, IN 46408				108			
Facility I.D. #: 11	505			İ	Phone #:							
This procedure is to test the leak integrity of single- and double-walled spill buckets. See PEI/RP1200 Section 6.2 for hydrostatic test method, Section 6.3 for single-walled vacuum test method and Section 6.4 for double-walled vacuum test method.												
Tank Number	1		2									
Product Stored	Regular		Premium									
Spill Bucket Capacity	5 gal		5 gal									
Manufacturer	OPW		OPW									
Construction	sw	•	sw	_	<u> </u>			•		Ť		
Test Type	Hydrostation	•	Hydrostati	_				•		Ť		
Spill Bucket Type	Product	•	Product	•	<u> </u>			•		·		
Liquid and debris removed from spill bucket?	Yes	•	Yes	•]			•		·		
Visual Inspection (No cracks, loose parts or separation of the bucket from the fill pipe.)	Pass	•	Pass	_				•		-		
Tank riser cap included in test?	Yes	•	Yes	-]. [V		V		
Drain valve included in test?	Yes	•	Yes	,		•		_		·		
Starting Level	11"		11"									
Test Start Time	1:25pm		1:35pm									
Ending Level	11"		8"									
Test End Time	2:25pm		2:35pm									
Test Period	1 Hr		1 Hr									
Level Change	0		-3"									
Pass/fail criteria: Must pass visual inspection. Hydrostatic: Water level drop of less than 1/8 inch; Vacuum single-walled only: Maintain at least 26 inches water column; Vacuum double-walled: maintain at least 12 inches water column.												
Test Results	Pass	•	Fail	,	<u>.</u>]. [•		v		
Comments:												
Tester's Name : Josh Rider Tester's Signature :												