Tanks Data	30 DAYS WALK THROUGH INSPECTION					
JST Facility I.D.( (FID) # <b>25595</b>	Contact Number					
Facility Name Mobil	Contact email					
Address 29026 CR-20 ElKhart 46517	Date of Inspection $6/7/23$					
Operator on Duty Name	Name of the Person Conducting Inspection  Josh			2ider		
Op	perator Train	ing		_	_	
Operator Training current	Yes	O <sub>No</sub>	OperatorNotified	Yes	ON <sub>0</sub>	
	tion/Notificat			0	0.	
Is Registration current with correct owner, operator etc.	Yes	Oy₀	OperatorNotified	Ves	$O_{10}$	
	elease Detecti	_	O	0.0	O.	
Release Detection Method	ATG	<b>CIM</b>	<b>SIR</b>	$O_{\rm IC}$	Other	
Make and Model	Franklin FS TS-550 evo				0	
Does it have paper?	Ves	$O_{N_0}$	OperatorNotified	Yes	Q√o	
Is it in Alarm mode?	O <sup>Yes</sup>	$O_{N^0}$	OperatorNotified	\(\int Yes\)	O <sub>10</sub>	
Interstitial Monitoring Sensor Status Normal	(V)'es	Olo	OperatorNotified	O'es	Olo	
Necessary Monthly Printout Taken	Yes	ONo.	OperatorNotified	O'es	O <sub>V</sub> o	
	Spill Bucket	s			_	
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	(V)Vo	<b>OperatorNotified</b>	(Ves	Olo	
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	$\bigcirc$ No	<b>OperatorNotified</b>	Ces	No	
	Fill Ports	0		0		
Is Fill pipe cap tight and fill pipe free from any obstruction?	Ves	Ovo	OperatorNotified	(Tes	Olo	
	iping/STP Su			~		
Are Sumps Clean and free from water, debris, product etc?	Yes	$\bigcirc$ 10	OperatorNotified	<b>⊘</b> /es	Olo	
	enser Contair	ments (UDC)			0	
Are UDCs clean and free from water, debris, product etc?	Yes	$\bigcirc$ No	OperatorNotified	(V) res	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	POSSED OFF OCEDUE BY A	ACCORDING 4 CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS	
Operator on Duty Name		Signature		Date		
317-645-0215 tanks	tanksdata@gmail.com				www.tanksdata.com	
					2022	