Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.( (FID) # 25298	Contact Nu	Contact Number			
Facility Name ARCO	Contact email				
Address 5034 E Raymond St Indianapolis	Date of Inspection 3/a			/23	
Operator on Duty Name 46203	Name of the Person Conducting Inspection  Josh				
Ор	erator Train				
Operator Training current	Yes	ON <sub>o</sub>	OperatorNotified	Yes	O <sub>No</sub>
Registrat	tion/Notifica	tion Form		_	_
Is Registration current with correct owner, operator etc.	Yes	$\bigcirc$ 40	OperatorNotified	()res	Olo
	lease Detecti				
Release Detection Method	<b>√</b> ATG	<b>CIM</b>	SIR	Oic	Other
Make and Model	VR TLS- 450		50	_	
Does it have paper?	Yes	O <sub>No</sub>	OperatorNotified	Yes	Oto
Is it in Alarm mode?	Yes	(V)No	OperatorNotified	Yes	O₁0
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	Olo
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	No
	Spill Bucket	s		0	_
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(No	OperatorNotified	(Ves	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	No
	Fill Ports	0			0.
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V)Yes	O/o	OperatorNotified	Tes	Oyo.
Pij	ping/STP Su	mps			
Are Sumps Clean and free from water, debris, product etc?	O <sub>Yes</sub>	$\bigcirc$ $^{10}$	OperatorNotified	(V)res	No
Under Dispe	nser Contair	ments (UDC)			0
Are UDCs clean and free from water, debris, product etc?	Yes	(V)Vo	OperatorNotified	(V) res	No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF CEDUE BY A	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name	Signature			Date	
317-645-0215 tankso	data@gmail.com			www.tanksdata.com	