Tanks Data	30 DAYS WALK THROUGH INSPECTION				
ST Facility I.D.((FID) # 25298	Contact Number				
acility Name ARCO	Contact email				
ddress 5034 E Raymond St Indianapolis 46203	Date of Inspection 7/14/23				
perator on Duty Name	Name of the Person Conducting Inspection Josh 4			Rider	
Op	erator Train				
Operator Training current	Oyes	No	OperatorNotified	Yes	No
Registra	tion/Notifica	tion Form	·	_	
Is Registration current with correct owner, operator etc.	Yes	O_{N^0}	OperatorNotified	O'es	No
	elease Detecti	on			_
Release Detection Method	⊘ ATG	CIM	SIR	Orc	Other
Make and Model	VR	TLS-450		•	_
Does it have paper?	Yes	O _N o	OperatorNotified	Yes	\bigcirc Vo
Is it in Alarm mode?	(V)Yes	ON ₀	OperatorNotified	Yes	No
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	Yes	N _o	OperatorNotified	Yes	No
	Spill Bucket	s			
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	No	OperatorNotified	Ces	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(V)/es	\sim_{N_0}	OperatorNotified	Zes .	\aleph_0
	Fill Ports	0		O.	0.0
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V)Yes	O\o	OperatorNotified	(Tes	Olo
	ping/STP Su	nps			0.
Are Sumps Clean and free from water, debris, product etc?	Ores	(V)Vo	OperatorNotified	(Ves	No
Under Dispe	enser Contair	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	OYes	\bigcirc No	OperatorNotified	(V)'es	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF CEDUE BY A	ACCORDING ACERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name	Signature			Date	
317-645-0215 tanksdata@gmail.com				www.tanksd	ata com