Tanks Data	3	80 DAYS W	ALK THROUGH	HINSPE	CTION
UST Facility I.D.((FID) # 25298	Contact No	Contact Number			
Facility Name ARCO	Contact email				
Address 5034 E Raymond St Indianapolis 46203	Date of Inspection $9/26/2$				
Operator on Duty Name	Name of the Person Conducting Inspection		Josh Rider		
0	perator Train				
Operator Training current	Yes	No	OperatorNotified	Yes	No
Registra	ation/Notifica	tion Form		0	_
Is Registration current with correct owner, operator etc.	Yes	Oylo	OperatorNotified	Ves	Olo
	elease Detect				0
Release Detection Method	√ ATG	CIM	SIR	OIC	Other
Make and Model	VR TLS-450				
Does it have paper?	Yes	ONo.	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	No
	Spill Bucket	s			0
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	(7)es	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	es	XI.o
	Fill Ports	0		O	0.0
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V)Yes	No	OperatorNotified	Tes	Olo
P	iping/STP Su	mps			
Are Sumps Clean and free from water, debris, product etc?	Yes	Olo	OperatorNotified	(V)Yes	No
Under Disp	enser Contain	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	(V)No	OperatorNotified	OYes	OVO.
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISI FOLLOWING PROPER PRO	POSSED OFF OCEDUE BY	ACCORDING 4 CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanks	sdata@gmail.com			www.tanksdata.com	