Tanks Data	30 DAYS WALK THROUGH INSPECTION					
UST Facility I.D.((FID) # a5a98	Contact Number					
Facility Name ARCO	Contact email					
Address 5034 E Raymond St Indianapolis 46203	Date of Inspection 1/9/24					
Operator on Duty Name	Name of the Person Conducting Inspection Josh Ride			_		
	Conducting	Conducting Inspection JOSA RIGEY				
	perator Train	ning		_		
Operator Training current	Yes	ON ₀	OperatorNotified	Yes	O _N o	
	tion/Notifica	tion Form		^		
Is Registration current with correct owner, operator etc.	Yes	O _N o	OperatorNotified	Ves	\bigcirc 10	
	elease Detect	_			_	
Release Detection Method	√ ATG	CIM	SIR	OIC	Other	
Make and Model	VR	TLS-450)			
Does it have paper?	Yes	O _N o	OperatorNotified	Yes	O10	
Is it in Alarm mode?	Yes	(V)No	OperatorNotified	Ores	Olo	
Interstitial Monitoring Sensor Status Normal	(V)es	O ₁₀	OperatorNotified	O'res	Olo	
Necessary Monthly Printout Taken	(V)Yes	ON _o	OperatorNotified)res	Olo	
	Spill Bucket	ts	-1	_		
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	minim	OperatorNotified	(Ves	Olo	
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	es	No	
And the second s	Fill Ports	0		0		
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V)Yes	$O_{N^{\circ}}$	OperatorNotified	(Tes	Olo	
Pi	ping/STP Su	mps		_		
Are Sumps Clean and free from water, debris, product etc?	Yes	\bigcirc 10	OperatorNotified	(V)res	No	
Under Dispe	enser Contain	nments (UDC)				
Are UDCs clean and free from water, debris, product etc?	OYes	(No	OperatorNotified	(V)res	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF OCEDUE BY .	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	ILATIONS	
Operator on Duty Name	Signature			Date		
317-645-0215 tankso	data@gmail.com			www.tanksdata.com		