

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (RID) # 252298

Facility Name ARIO

Address 5034 E Raymond St, Indiana, PA 15110

Operator on Duty Name W 46203

Contact Number

Contact email

Date of Inspection 09/24/24

Name of the Person Conducting Inspection AKSMIT

Operator Training current

Operator Training

Operator Notified

Yes

No

Is Registration current with correct owner, operator etc.

Registration/Notification Form

Operator Notified

Yes

No

Release Detection Method

Release Detection

Operator Notified

Yes

No

Make and Model

ATG

Operator Notified

Yes

No

Does it have paper?

Yes

Operator Notified

Yes

No

Is it in Alarm mode?

Yes

Operator Notified

Yes

No

Interstitial Monitoring Sensor Status Normal

Yes

Operator Notified

Yes

No

Necessary Monthly Printout Taken

Yes

Operator Notified

Yes

No

Are Spill Buckets Clean and free from water, debris, product etc?

Yes

Operator Notified

Yes

No

Are the Spill Bucket in good condition and free of damage/cracks

Yes

Operator Notified

Yes

No

Is Fill pipe cap tight and fill pipe free from any obstruction?

Yes

Operator Notified

Yes

No

Are Sumps Clean and free from water, debris, product etc?

Yes

Operator Notified

Yes

No

Are UDCs clean and free from water, debris, product etc?

Yes

Operator Notified

Yes

No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

317-645-0215

Signature

tanksdata@gmail.com

Date

www.tanksdata.com

20220516