		30 DAYS V	VALK THROUG	HINSPE	CTION	
Tanks Data  UST Facility I.D.((FID) # 25298	The same of the sa	Contact Number  Contact email				
Facility Name AR (O) Address 5034 ERAymond 544670	6703 Date of Inspection 69-08-200					
Operator on Duty Name	Conducting Operator Traini	Inspection	Gruppe			
The indicate autront	Yes	No	OperatorNotified	OYes	ON <sub>o</sub>	
Registra	ation/Notificati	ONO.	OperatorNotified	()Yes	$\bigcirc$	
Release Detection Method	Release Detection	© CIM	OSIR	Orc	Other	
Make and Model UR TCS - 7.  Does it have paper?  Is it in Alarm mode?	Yes	QNo No	OperatorNotified OperatorNotified	Yes Yes Yes	01° 01° 01°	
Interstitial Monitoring Sensor Status Normal Necessary Monthly Printout Taken	Yes Yes Spill Buckets	SN° ON°	OperatorNotified OperatorNotified	Ö'es	Oio Oio	
Are Spill Buckets Clean and free from water, debris, product etc?  Are the Spill Bucket in good condition and free of damage/cracks	Yes Yes Fill Ports	SNo SNo	OperatorNotified OperatorNotified	es es	8	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes ing/STP Sump	ONO S	OperatorNotified	Oes	ON°	
Are Sumps Clean and free from water, debris, product etc?  Under Dispen	Yes	O\ro	OperatorNotified	Yes	ONO	
range along and free from water debris, product etc?	Yes	No	OperatorNotified	Ores	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOS FOLLOWING PROPER PROCE	SSED OFF ACE	CORDING T ERTIFIED C	O EXISTING RULES A ONTRACTOR.	IND REQUI	LATIONS	
rator on Duty Name		Signature		Date		
317-645-0215 tanksdat	ta@gmail.com	1		www.tanksd	iata.com 20220516	