Tanks Data	3	0 DAYS W	ALK THROUGH	INSPEC	CTION
ST Facility I.D.((FID) # 2986	Contact Number				
ncility Name Marathon	Contact email				
ddress 2101 E Michigan Blvd Michigan City	Date of Inspection 9/11/23				
perator on Duty Name 46360	Name of the Person Conducting Inspection Josh		lider		
Ор	erator Train	ing			
Operator Training current	Yes	ΟNo	OperatorNotified	Yes	(No
Registrat	tion/Notifica	tion Form		~	_
Is Registration current with correct owner, operator etc.	Yes	Oyo	OperatorNotified	Ves	Olo
	elease Detect	_	_	_	_
Release Detection Method	ATG	C IM	SIR	OIC	Other
Make and Model	VR	TLS- 35	50		_
Does it have paper?	Yes	ONo	OperatorNotified	Yes	Oto
Is it in Alarm mode?	Yes	(V)No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Ores	Olo
Necessary Monthly Printout Taken	Yes	\bigcirc No	OperatorNotified	Yes	No
	Spill Bucket	s			
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	(V)Vo	OperatorNotified	(Ves	No
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	es	No
	Fill Ports	0		0	
Is Fill pipe cap tight and fill pipe free from any obstruction?	(Ves	Ovo	OperatorNotified	()es	Olo
Pi	ping/STP Su	mps		_	
Are Sumps Clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified	Ves	No
Under Dispe	enser Contain	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	⊘ No	OperatorNotified	(V)'es	No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF OCEDUE BY	ACCORDING 4 CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
perator on Duty Name		Signature		Date	
317-645-0215 tanks	data@gmail.c	om		www.tanks	data.com