

Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) #	2986	Contact Number	
Facility Name	Mageshen	Contact email	
Address	9101 E. McClellan Blvd, N. 4630	Date of Inspection	3/26/2023
Operator on Duty Name	City, IN	Name of the Person Conducting Inspection	V. A. R. E. V. E. N. E. N.
Operator Training			
Operator Training current	☒ Yes	☐ No	Operator/Notified ☐ Yes ☐ No
Registration/Notification Form			
Is Registration current with correct owner, operator etc.	☐ Yes	☐ No	Operator/Notified ☐ Yes ☐ No
Release Detection			
Release Detection Method	☐ ATG	☐ DIM	☐ SIR
Make and Model	VLT 350		
Does it have paper?	☒ Yes	☐ No	Operator/Notified ☐ Yes ☐ No
Is it in Alarm mode?	☐ Yes	☒ No	Operator/Notified ☐ Yes ☐ No
Interstitial Monitoring Sensor Status Normal	☐ Yes	☒ No	Operator/Notified ☐ Yes ☐ No
Necessary Monthly Printout Taken	☒ Yes	☐ No	Operator/Notified ☐ Yes ☐ No
Spill Buckets			
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes	☐ No	Operator/Notified ☐ Yes ☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes	☐ No	Operator/Notified ☐ Yes ☐ No
Fill Ports			
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes	☐ No	Operator/Notified ☐ Yes ☐ No
Piping/STP Sumps			
Are Sumps Clean and free from water, debris, product etc?	☐ Yes	☒ No	Operator/Notified ☐ Yes ☐ No
Under Dispenser Containers (UDC)			
Are UDCs clean and free from water, debris, product etc?	☐ Yes	☒ No	Operator/Notified ☐ Yes ☐ No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.			
Operator on Duty Name	Signature		Date
317-645-0215	tanksdata@gmail.com		www.tanksdata.com