

000

30 DAYS WALK THROUGH INSPECTION

Tanks Data	
UST Facility I.D. (FID) #	2986
Facility Name	MFRAT 110 N
Address	2101 E Michigan Blvd, Michigan
Operator on Duty Name	City, IN 46360
Contact Number	
Contact email	
Date of Inspection	10/14/24
Name of the Person Conducting Inspection	AKSHIT
Operator Training	
Operator Training current	☒ Yes ☐ No
Is Registration current with correct owner, operator etc.	☒ Yes ☐ No
Release Detection	
Release Detection Method	☒ ATG ☐ CIM ☐ SIR
Make and Model	VRTS-1350
Does it have paper?	☒ Yes ☐ No
Is it in Alarm mode?	☒ Yes ☐ No
Interstitial Monitoring Sensor Status Normal	☒ Yes ☐ No
Necessary Monthly Printout Taken	☒ Yes ☐ No
Spill Buckets	
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes ☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes ☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes ☐ No
Are Sumps Clean and free from water, debris, product etc?	☒ Yes ☐ No
Under Dispenser Containments (UDC)	
Are UDCs clean and free from water, debris, product etc?	☒ Yes ☐ No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.	
Operator on Duty Name	
Signature	
Date	
317-645-0215	
tanksdata@gmail.com	
www.tanksdata.com	
20220516	