Tanks Data	3	0 DAYS W	ALK THROUGH	IINSPEC	TION
UST Facility I.D.((FID) # 2 9 4 1	Contact Number				
Facility Name 11 12 20thon	Contact email				
Address 710/ F Mi-Linem R1 (104)	26 Pate of Inspection (2) 8-11-2025				
Operator on Duty Name	Name of the Person Conducting Inspection Gurbreet				
	perator Train				
Operator Training current	Yes	No	OperatorNotified	Yes	No
[19일일] 하를 되었는데 10일	ation/Notificat	tion Form		_	
Is Registration current with correct owner, operator etc.	Yes	ONO	OperatorNotified	O'res	Olo
I	Release Detecti	on			
Release Detection Method	ATG	CIM	SIR	OIC	Other
Make and Model / RTZS	358				
Does it have paper?	Yes	ONO	OperatorNotified	Yes	\mathcal{L}_{10}
Is it in Alarm mode?	Yes	ONo	OperatorNotified	Yes	QVo
Interstitial Monitoring Sensor Status Normal	Yes	ONO	OperatorNotified	Yes	Ovo
Necessary Monthly Printout Taken	Yes	ON0	OperatorNotified	Yes	Olo
맞았다. IN ANT CONTROL OF A STATE OF Barrier of Anti-Anti-Anti-Anti-Anti-Anti-Anti-Anti-	Spill Buckets	s		^	
Are Spill Buckets Clean and free from water, debris, product etc?		No	OperatorNotified	es	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Yes	ONo	OperatorNotified	es	Olo
	Fill Ports			~	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Ovo	OperatorNotified	Oes	Olo
P	piping/STP Sur	nps			
Are Sumps Clean and free from water, debris, product etc?	Yes	(O)Vo	OperatorNotified	Yes	Oyo
Under Disp	enser Contain	ments (UDC)		~	
Are UDCs clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified		Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISE FOLLOWING PROPER PRO	POSSED OFF A	ACCÒRDING I CERTIFIED (TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature	4	Date	
를 보고 하는 보고 있다. 그는 사람들은 사람들은 보고 있는 것으로 가는 사람들이 되었습니다. 그리고 있는 사람들이 되었습니다. 그리고 있는 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은	sdata@gmail.c	om		www.tankso	lata.com
					202205