Tanks Data	30 DAYS WALK THROUGH INSPECTION
UST Facility I.D.((FID) # 2986	Contact Number
Facility Name Marathan	Contact email
Address 2101 E Michigan 15L	
Operator on Duty Name	Name of the Person Conducting Inspection Gurebraet
	Operator Training
Operator Training current	Oyes ONo OperatorNotified Oyes ONo
	Registration/Notification Form
Is Registration current with correct owner, or	perator etc. OYes ONo OperatorNotified OYes ONO
	Release Detection
Release Detection Method	OATG OIM OBIR OIC Other
Make and Model	
Does it have paper?	Wes ONo OperatorNotified Ores O
Is it in Alarm mode?	OYes ONo OperatorNotified OYes ONO
Interstitial Monitoring Sensor Status	Normal Yes Wo OperatorNotified Yes No
Necessary Monthly Printout Take	en Spill Buckets Ovo Operator Notified Oes Ovo
Are Spill Buckets Clean and free from water, de	에 <del>하는데 이 사용을 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데</del>
Are the Spill Bucket in good condition and free	하는 아이들이 많은 사람들이 나는 아이들이 살아보니 아니를 아니는
Is Fill pipe cap tight and fill pipe free from a	다른 사람들은 그는 사람들이 되었다면 하는 사람들이 되었
	Piping/STP Sumps
Are Sumps Clean and free from water, debri	is, product etc? OYes ONO OperatorNotified OYes No
	Under Dispenser Containments (UDC)
Are UDCs clean and free from water, deb	oris, product etc? Ores One Operator Notified Ores Ores
HDG (1988) 이 1988 (1988) 전 1988 (1988) 이 1988 (1988) - 1988 (1988) 전 19	ASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS WING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.
Operator on Duty Name	Signature
317-645-0215	tanksdata@gmail.com www.tanksdata.com
	20220516