

Petroleum Testing Services

PO BOX 146
Yorktown, IN 47396
(765) 749-5540

Email: petroleumtesting@aol.com

DATE: 12-27-2021	TIME:4:00P
SITE ADDRESS Simars 206 N Benton Millersburg, IN 46543	

SPILL BUCKET INTEGRITY TEST

TANK	1	2	3	4
PRODUCT	UNL	PREM	DSL	KERO
SPILL BUCKET CAPACITY	5	5	5	5
SINGLE/DOUBLE WALLED	S	S	S	S
LIQUID/DEBRIS REMOVED	Y	Y	Y	Y
VISUAL INSPECTION	OK	OK	OK	OK
TANK RISER CAP INCLUDED?	NO	NO	NO	NO
DRAIN VALVE INCLUDED?	NA	Y	Y	Y
STARTING LEVEL	12	8.75	9	9
TYPE OF TEST	H	H	H	H
ENDING LEVEL	12	8.75	9	9
TEST DURATION	1HR	1HR	1HR	1HR
LEVEL CHANGE	0	0	0	0
RESULT	PASS	PASS	PASS	PASS

OVERFILL INSPECTION

TANK #	1	2	3	
PRODUCT	UNL	PRE	DSL	KERO
TANK DIAMETER				
TANK VOLUME				
TYPE OF OVERFILL	BF	BF	BF	BF
OVERFILL MECHANISM IS FREE FROM DEBRIS				
OVERFILL MECHANISM MOVES FREELY				
TOP OF RISER TO TANK BOTTOM				
TOP OF RISER TO OVERFILL				
HT OF OVERFILL FROM TANK BOTTOM				
OVERFILL IS ADJUSTED TO 90% OF TANKS CAPACITY				
RESULT	*	*	*	*

*NO AUTOMATIC OVERFILL IS PRESENT. BALL FLOAT COULD NOT BE VERIFIED OR ACCESSED.

INSPECTED BY: RONNIE BROWN

UC2017IN12086