

000
Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (RID) # 2451	Contact Number
Facility Name MARRATHON	Contact email
Address 206 N Benton, Milesburg, PA	Date of Inspection 11/15/24
Operator on Duty Name 46543	Name of the Person Conducting Inspection AKSHIT

Operator Training current

Is Registration current with correct owner, operator etc.

Registration/Notification Form
☐ Yes ☐ No

Operator Notified
☐ Yes ☐ No

Release Detection Method

Make and Model

Does it have paper?

Is it in Alarm mode?

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

Release Detection
GATG ☐ TIM ☐ SIR ☐ C ☐ Other

FPS TS SEED

Spill Buckets

Are Spill Buckets Clean and free from water, debris, product etc?
Are the Spill Bucket in good condition and free of damage/cracks

Fill Ports
☒ Yes ☐ No

Operator Notified
☒ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

Piping/STP Sumps
☒ Yes ☐ No

Operator Notified
☒ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc?

Under Dispenser Containments (UDC)
☒ Yes ☐ No

Are UDCs clean and free from water, debris, product etc?

Operator Notified
☒ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com