

30 DAYS WALK THROUGH INSPECTION

Tanks Data

UST Facility I.D. (FID) # 24551

Contact Number

Facility Name MARRATHON

Contact email

Address 286 N Benton, Milesburg, PA

Date of Inspection 6/14/14

Operator on Duty Name

IN 46543

Name of the Person Conducting Inspection

AKSHIT SHARMA

Operator Training current

Operator Training

Operator Notified

Yes

No

Is Registration current with correct owner, operator etc.

Registration/Notification Form

Operator Notified

Yes

No

Release Detection Method

Release Detection

ATG

Yes

Other

Make and Model

FFS

SIR

Yes

No

Does it have paper?

Yes

Operator Notified

Yes

No

Is it in Alarm mode?

Yes

Operator Notified

Yes

No

Interstitial Monitoring Sensor Status Normal

Yes

Operator Notified

Yes

No

Necessary Monthly Printout Taken

Yes

Operator Notified

Yes

No

Spill Buckets

Yes

Operator Notified

Yes

No

Are Spill Buckets Clean and free from water, debris, product etc?

Yes

Operator Notified

Yes

No

Fill Ports

Yes

Operator Notified

Yes

No

Is Fill pipe cap tight and fill pipe free from any obstruction?

Yes

Operator Notified

Yes

No

Piping/STP Sumps

Yes

Operator Notified

Yes

No

Are Sumps Clean and free from water, debris, product etc?

Yes

Operator Notified

Yes

No

Under Dispenser Containments (UDC)

Yes

Operator Notified

Yes

No

Are UDCs clean and free from water, debris, product etc?

Yes

Operator Notified

Yes

No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tankdata@gmail.com

www.tankdata.com