

Oil
Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) # 24551	Contact Number
Facility Name MARATHON	Contact email
Address 206 N Benton, Milledgeville	Date of Inspection 07/22/21
Operator on Duty Name LW 46543	Name of the Person Conducting Inspection AKSHIT SARKAR

Operator Training current	☐ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Is Registration current with correct owner, operator etc.	☐ Yes	☐ No	Registration/Notification Form	☐ Yes	☐ No
Release Detection Method	☒ ATG	☐ CIM	Release Detection	☐ Yes	☐ No
Make and Model	IFS 550 EV2				
Does it have paper?	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Is it in Alarm mode?	☒ Yes	☐ No	Operator Notified	☒ Yes	☐ No
Interstitial Monitoring Sensor Status Normal	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Necessary Monthly Printout Taken	☐ Yes	☐ No	Operator Notified	☐ Yes	☐ No

Are Spill Buckets Clean and free from water, debris, product etc?	☐ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☐ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No

Are Sumps Clean and free from water, debris, product etc?	☐ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Under Dispenser Contaminants (UDC)	☐ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Are UDCs clean and free from water, debris, product etc?	☐ Yes	☐ No	Operator Notified	☒ Yes	☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name	Signature	Date
317-645-0215	tanksdata@gmail.com	www.tanksdata.com