

011  
Tank Data

30 DAYS WALK THROUGH INSPECTION

|                           |                          |                                          |          |
|---------------------------|--------------------------|------------------------------------------|----------|
| UST Facility I.D. (PID) # | 24551                    | Contact Number                           |          |
| Facility Name             | MARATHON                 | Contact email                            |          |
| Address                   | 206 N Benton, Milledushy | Date of Inspection                       | 10/23/24 |
| Operator on Duty Name     | IN 4 6573                | Name of the Person Conducting Inspection | AKSHIT   |

  

| Operator Training current                                         | Registration/Notification Form                                | Release Detection                                             | Operator Notified                                             | Operator Notified                                             |
|-------------------------------------------------------------------|---------------------------------------------------------------|---------------------------------------------------------------|---------------------------------------------------------------|---------------------------------------------------------------|
| Is Registration current with correct owner, operator etc.         | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            |
| Release Detection Method                                          |                                                               |                                                               |                                                               |                                                               |
| Make and Model                                                    |                                                               |                                                               |                                                               |                                                               |
| Does it have paper?                                               | <input checked="" type="radio"/> Yes <input type="radio"/> No | <input checked="" type="radio"/> Yes <input type="radio"/> No | <input checked="" type="radio"/> Yes <input type="radio"/> No | <input checked="" type="radio"/> Yes <input type="radio"/> No |
| Is it in Alarm mode?                                              | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            |
| Interstitial Monitoring Sensor Status Normal                      | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            |
| Necessary Monthly Printout Taken                                  | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            |
| Are Spill Buckets Clean and free from water, debris, product etc? | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            |
| Are the Spill Bucket in good condition and free of damage/cracks  | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            |
| Is Fill pipe cap tight and fill pipe free from any obstruction?   | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            |
| Are Sumps Clean and free from water, debris, product etc?         | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            |
| Under Dispenser Containments (UDC)                                | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            |
| Are UDCs clean and free from water, debris, product etc?          | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            | <input type="radio"/> Yes <input type="radio"/> No            |

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name: \_\_\_\_\_ Signature: \_\_\_\_\_ Date: \_\_\_\_\_

317-645-0215 tankdata@gmail.com www.tankdata.com