

30 DAYS WALK THROUGH INSPECTION

all
Tanks Data

UST Facility ID (FID) # 24551

Facility Name MARRATHON

Address 206 N Benton, Millersburg

Operator on Duty Name L. H. 4543

Contact Number

Contact email

Date of Inspection 09/14/25

Name of the Person Conducting Inspection AKSMT

Operator Training current

Is Registration current with correct owner, operator etc.

Registration/Notification Form

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ Other

Release Detection Method

Make and Model

Does it have paper?

Is it in Alarm mode?

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

Release Detection

☒ ATG ☐ DM

FPS TSS2FLD

☐ SIR

☐ JC

☐ Other

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ Other

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ Other

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ Other

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ Other

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ Other

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ Other

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ Other

Operator on Duty Name

Signature

Date

www.tankdata.com