

Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D.(FID) # 24551
 Facility Name Martinez
 Address 206 N Denton 46943
 Operator on Duty Name

Contact Number
 Contact email
 Date of Inspection 08-28-2025
 Name of the Person Conducting Inspection Garipreet

Operator Training current	Operator Training ☐ Yes ☐ No		Operator Notified	☐ Yes	☐ No
Is Registration current with correct owner, operator etc.	Registration/Notification Form ☐ Yes ☐ No		Operator Notified	☐ Yes	☐ No
Release Detection Method	Release Detection ☒ ATG ☒ CIM		☐ SIR	☐ IC	☐ Other
Make and Model <u>TS-550 EVO</u>			Operator Notified	☐ Yes	☐ No
Does it have paper?	☒ Yes ☐ No		Operator Notified	☐ Yes	☐ No
Is it in Alarm mode?	☐ Yes ☒ No		Operator Notified	☐ Yes	☐ No
Interstitial Monitoring Sensor Status Normal	☒ Yes ☐ No		Operator Notified	☐ Yes	☐ No
Necessary Monthly Printout Taken	☒ Yes ☐ No		Operator Notified	☐ Yes	☐ No
Are Spill Buckets Clean and free from water, debris, product etc?	Spill Buckets ☐ Yes ☒ No		Operator Notified	☒ Yes	☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes ☐ No		Operator Notified	☐ Yes	☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction?	Fill Ports ☐ Yes ☐ No		Operator Notified	☐ Yes	☐ No
Are Sumps Clean and free from water, debris, product etc?	Piping/STP Sumps ☐ Yes ☒ No		Operator Notified	☒ Yes	☐ No
Are UDCs clean and free from water, debris, product etc?	Under Dispenser Containments (UDC) ☐ Yes ☒ No		Operator Notified	☒ Yes	☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

317-645-0215

Signature

Date

tanksdata@gmail.com

www.tanksdata.com