Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 18406	Contact Number				
Facility Name Marathon	Contact ema	Contact email			
Address 2068 E Market St Nappanee 46550	Date of Insp	Date of Inspection 9/1/2			
Operator on Duty Name	Name of the	Nama of the Dames		ider	
Or	erator Traini	_			
Operator Training current	Yes	No	OperatorNotified	Yes	No
Registra	tion/Notification	n Form		0	
Is Registration current with correct owner, operator etc.	Yes	ONO	OperatorNotified	O'res	Olo
	elease Detectio	n		_	
Release Detection Method	ATG	CIM	SIR	Orc	Other
Make and Model	Franklin	FS	TS- 750		
Does it have paper?	(V)Yes	ONo.	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Yes	(V)No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	Olo
Necessary Monthly Printout Taken	Cycs	No	OperatorNotified	Yes	No
	Spill Buckets				
Are Spill Buckets Clean and free from water, debris, product etc?	O'es	No	OperatorNotified	(V)es	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(V)res	No	OperatorNotified	es	Olo
	Fill Ports	0			
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V)/es	O/o	OperatorNotified	(Tes	Oto
Pip	ing/STP Sump	5		~	
Are Sumps Clean and free from water, debris, product etc?	O'res	⊘ /10	OperatorNotified	Vres	Olo
Under Dispen	ser Containm	ents (UD	C)	-/	
Are UDCs clean and free from water, debris, product etc?	OYes .	\bigcirc No	OperatorNotified	Yes	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PROC	SSED OFF AC	CORDIN ERTIFIE	G TO EXISTING RULES . D CONTRACTOR.	AND REQU	LATIONS
perator on Duty Name		Signatur	e	Date	
317-645-0215 tanksda	tanksdata@gmail.com			www.tanksdata.com	
	00				20

SIMAR 2068 E MARKET ST NAPPANEE IN 46550 574-773-0344

09/01/2022 8:56 AM

SCALD TEST REPORT

DIESEL 10205,3 GAL DIESEL

SLOPE -0,007 GAL/HR TEST RESULT PASSED SLOPE EQUALS CALCULATED LEAK RATE

UNLEAD 10205, 3 GAL ULEADED

LEAK TEST 0, 200 GPH
LEAK THRESHOLD 0, 100 GPH
INTERVAL 18, 0
VOL QUALIFY 0, 0%
TEST STARTED 1:25 AM
TEST STARTED 09/01/2022
STATUS 0, 0, 02
TEST ENDED 3:28 AM
TEST ENDED 09/01/2022

SLOPE -0,066 GAL/HR TEST RESULT PASSED SLOPE EQUALS CALCULATED LEAK RATE