

5296 Breakers Way, Carmel, IN 46033

www.tanksdata.com
tanksdata@gmail.com
(317)-300-6065

Date

9/13/24

UST Annual Walkthrough Inspection

1. UST Facility Information													
Facility I.D. #:	18406												
UST Facility Name	Marathon												
UST Facility Physical Address	Street Address :	2068 E Market St	City:	Nappanee	Zip Code :	IN, 46550							

2. Annual Inspection Checklist

Category	Description		N/A			Tank 2		Tank 3		Tanl	_	Tank 5	Tan	Tank 6		Tank 7		8
				Re	Reg		Prem		Dies		0							
	Cap in good condition, seals tightl probe wire goes through	y, hole sealed where		Yes	•	Yes	•	Yes	•	Yes	•			•		•	•	•
ATG Manhole	Junction box has cover, not corroded; intrinsically safe wiring in good condition			Yes	•	Yes	•	Yes	•	Yes	•].	•		•	-	•
A 1 G Mannole	Manhole cover in good condition			Yes	V	Yes	•	Yes	•	Yes	•].	V		•		•
	Functionality Test Date :	9/13/24		-	•		•		•		•			•		•		•
	Single-walled spill containment manhole tightness tested within last 3 years			Yes	•	Yes	•	Yes	•	Yes	•			•		•		•
	Double-walled spill containment manhole tightness tested within last 3 years OR inspected monthly		~	•	•		•		•		•	. [•	. [•		•
Spill Bucket	Are spill buckets free of product, water and debris?			Yes	▼	Yes	•	Yes	•	Yes	•			•	. [•	•	•
	Are spill buckets free of damage/cracks?			Yes	•	Yes	•	Yes	•	Yes	•	. 🔽	<u> </u>	V	. [—		•
	HSB Test Date :	9/13/24			•		•		•	u.	•			•		•		•
	Drop tube shutoff valve passes inspection & excessive corrosion not present			Yes	•	Yes	•	Yes	•	Yes	•	. [_		•		•
Overfill	Ball float valve passes inspection, can be removed & excessive corrosion not present		~		•		•		•		•	. [•	•	•		•
Prevention	Overfill alarm passes inspection		~	•	▼		~].	•		•].	•		•		•
	OPV Test Date :	9/13/24			•		•		•	·	•			•		•		•
	Galvanic Cathodic Protection test has been conducted within the past 3 years and the test passed		~		•		•		•		•					•		•
Corrosion	•	Impressed Current Cathodic Protection test has been conducted within the past 3 years and the test passed			•		•		•		•			•	-	•		•
Protection	Tank Lining inspected as required	and in good condition	~		•		•	ļ	•		•			•		•		•
	CP Test Date :		~		•		•		•		•			•		•	•	•

Category	Category Description		N/A	/A Tank1		Tank 2		Tank 3 Dies		Tank4 Kero		Tank 5	To	ınk 6	Tank 7		Tank 8	
				Reg		Prer	m											
	12 Months of RD printed and on site			No		No	lacksquare	No	-	No	•	. [·].	lacksquare	. [<u> </u>	V	
	Release Detection Report have issues i	n past months		No	_	No	•	No	•	No	•	. [1	~		₹.	-	
Release Detection	ATG console has any history of alarm i	n past months		No	~	No	lacksquare	No	•	No	•	. [<u>]</u> .		. [▼].		
	Release Detection Type :	ATG			•	•	•		•	•	•			•		-	_	
	Liquid and debris removed from sump	?		Yes	•	Yes	•	Yes	•		•		<u>.</u>	_		▼].	lacksquare	
Containment Sumps	Are containment sumps free of damag	ge/cracks?		Yes	•	Yes	_	Yes	•	•	•		·].	_	. [V	
	HSC Test Date :				•		•		•	•	•		<u> </u>	•		▼].	_	
Stage I Testing	Verify that Stage I testing has been corresults are passing	nducted and test	~		•	•	_	. [•	-	•			•	. [▼].	_	
Comments/I	Deficiencies:																	
Name (Class A & B Operator) :																		
Name (Person conducted the inspection) :								Josh	Ric	der								
Signature (Person conducted the inspection):																		