Tanks Data	30 DAYS WALK THROUGH INSPECTION
UST Facility I.D.((FID) # 18406	Contact Number
Facility Name hashboy	Contact email
Address 2068 E market 5+ 46550	Date of Inspection $06-30-7025$
Operator on Duty Name	Name of the Person Conducting Inspection Guybaot
Ор	perator Training
Operator Training current	Oyes Ono Operator Notified Oyes Ono
Registrat	tion/Notification Form Operator Notified (Yes (No
Is Registration current with correct owner, operator etc.	OYes ONO Operator Notifica
Re	elease Detection OIC Other
Release Detection Method Make and Model 75 -750 7A	DATG CIM COM
Make and Model 15-750 1 H	Ores No Operator Notified Ores Oo
Does it have paper?	
Is it in Alarm mode?	(7) cs One operation ×
Interstitial Monitoring Sensor Status Normal	O'es O'o Operator Notified Yes O'o
Necessary Monthly Printout Taken	Yes No OperatorNotified Yes No
Spill Buckets	
Are Spill Buckets Clean and free from water, debris, product etc?	Ores To Operator Notified Tes
Are the Spill Bucket in good condition and free of damage/cracks	
	Fill Ports
Is Fill pipe cap tight and fill pipe free from any obstruction?	Ores No OperatorNotified Oes No
Pip	iping/STP Sumps Operator Notified (Yes No
Are Sumps Clean and free from water, debris, product etc?	Ores Ores
Under Dispe	enser Containments (UDC)
Are UDCs clean and free from water, debris, product etc?	Oyes No Operator Notified Oyes No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.	
Operator on Duty Name	Signature
. [집단 : [집] [[[[[[[[[[[[[[[[[sdata@gmail.com