Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 2871	Contact Number				
Cacility Name Conoco	Contact email				
Address 104 E Lincolnway La Porte 46350	Date of Inspection 7/5/23				
Operator on Duty Name	Name of the Person Conducting Inspection Josh			Rider	
0	perator Train	ing			
Operator Training current	Oyes	ON ₀	OperatorNotified	Yes	Oyo
Registra	tion/Notificat	ion Form		_	_
Is Registration current with correct owner, operator etc.	Yes	Oyo	OperatorNotified	Ves	Oıo
	elease Detecti	_		_	_
Release Detection Method	⊘ ATG	C IM	O SIR	Oic	Other
Make and Model	VR	TLS-350			_
Does it have paper?	Yes	O _N o	OperatorNotified	Yes	\bigcirc 10
Is it in Alarm mode?	Yes	(V)No	OperatorNotified	OYes	\bigcirc 10
Interstitial Monitoring Sensor Status Normal	Yes	O\o	OperatorNotified	Ores	Oio
Necessary Monthly Printout Taken	Yes	\bigcirc No	OperatorNotified	Ores	Olo
	Spill Bucket	, O			
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(V)vo	OperatorNotified	(V)es	\bigcirc 10
Are the Spill Bucket in good condition and free of damage/cracks	(V)res	\bigcirc No	OperatorNotified	Ces	⊘ 10
	Fill Ports	0		_	~
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	O ₁₀	OperatorNotified	Oes	\bigcirc 10
	ping/STP Sur			~	
Are Sumps Clean and free from water, debris, product etc?	Ves	\bigcirc 10	OperatorNotified	(√Yes	Olo
Under Dispo	enser Contain	ments (UDC)		_	
Are UDCs clean and free from water, debris, product etc?	OYes .	⊘ /0	OperatorNotified	⊘ res	O_{l^0}
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISF FOLLOWING PROPER PRO	POSSED OFF . OCEDUE BY A	ACCORDING CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanksdata@gmail.com				www.tanksdata.com	