Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 8871	Contact Number				
Facility Name Conoco	Contact email				
Address 104 E Lincolnway La Porte 46350	Date of Inspection 2/9/24			1	
Operator on Duty Name	Name of the Person Conducting Inspection Josh				
Op	erator Train	ing			
Operator Training current	Oyes	ON _o	OperatorNotified	Yes	ONo
Registrat	tion/Notifica	tion Form		_	_
Is Registration current with correct owner, operator etc.	Yes	O_{N_0}	OperatorNotified	Ves	Olo
	lease Detect	_		_	
Release Detection Method	⊘ ATG	C IM	SIR	Oic	Other
Make and Model	VR TLS-350				
Does it have paper?	Yes	O_{N_0}	OperatorNotified	Yes	\bigcirc Vo
Is it in Alarm mode?	(V)Yes	O_{No}	OperatorNotified	 ✓ Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	O/o	OperatorNotified	Yes	Oyo
Necessary Monthly Printout Taken	(V)Yes	\bigcirc No	OperatorNotified	O'res	\bigcirc Vo
	Spill Bucket	s minir	nal	_	
Are Spill Buckets Clean and free from water, debris, product etc?	Ores	(No	OperatorNotified	(V)es	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	Čes	No
	Fill Ports	0		0	0
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V)Yes	Olo	OperatorNotified	Tes	Olo
Pip	oing/STP Su	mps		_	_
Are Sumps Clean and free from water, debris, product etc?	√ Yes	Olo	OperatorNotified	O'res	Olo
Under Dispe	nser Contair	ments (UDC			
Are UDCs clean and free from water, debris, product etc?	Yes	Ø√o	OperatorNotified	(V)res	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO	OSSED OFF CEDUE BY A	ACCORDING 4 CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
perator on Duty Name	Signature			Date	
317-645-0215 tanksc	tanksdata@gmail.com			www.tanksdata.com	