

30 DAYS WALK THROUGH INSPECTION

UST Facility ID (RID) # 2871

Facility Name Garage

Address 104 Lincolnway E, La Porte

Operator on Duty Name LN46350

Contact Number

Contact email

Date of Inspection 11/13/21

Name of the Person

Conducting Inspection AKSMT

Operator Training current

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Is Registration current with correct owner, operator etc.

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Release Detection Method

☒ ATG ☐ TIM

☐ BIR

☐ IC

☐ Other

Make and Model

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Does it have paper?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Is it in Alarm mode?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Interstitial Monitoring Sensor Status Normal

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Necessary Monthly Printout Taken

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Are Spill Buckets Clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Are the Spill Bucket in good condition and free of damage/cracks

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Are UDCs clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

317-645-0215

Signature

tanksdata@gmail.com

www.tanksdata.com

20220516