TANK PRESSURE CALCULATION and WATER SENSOR CALIBRATION Midwest Tank Testing **EZY CHEK SYSTEMS** 316 W. Indiana Ave. **FINAL REPORT** Chesterton, IN 46304 PC # and WO # NAME and FID # FID # 2871 104 E Lincolnway **ADDRESS** La Porte IN 46350 CITY/STATE/ZIP CONTACT **PHONE** THE ACOUSTIC CHARACTERISTIC OF A LEAK REVEALS: PASS TIGHT TANK THIS UNDERGROUND STORAGE TANK PASSES / FAILS THE CRITERIA SET FORTH BY THE U.S. EPA. PASS **ULLAGE (DRY) PORTION OF LEAK** THIS UNDERGROUND STORAGE TANK PASSES / FAILS THE CRITERIA SET FORTH BY THE U.S. EPA. PASS BELOW PRODUCT LEVEL (WET) PORTION LEAK

V	VATER SENSOR CALIE	BRATION	
	DATE AND TIME	8/15/22 1	100-1400
	WEATHER	80 Sı	unny
	INVOICE	COLI	LECT
	TOTAL TANK VOL.		
	PRODUCT VOL.		
	ULAGE VOL.		
	PRODUCT TYPE	Reg	ular
	TANK#	,	1
Depth of Groundwater Determi		ter Determined:	5
	BY:	STICK	
	WHERE:	MONITORING W	ELL - TANK BED

THIS UNDERGROUND STORAGE TANK PASSES / FAILS THE CRITERIA SET FORTH BY THE U.S. EPA.

WATER SENSOR INDICATES:

(MARK ONLY ONE)

No Water Intrusion **Water Intrusion** Not Applicable

OPERATOR INFO

Print Name	Seth Lynn	Certification #	ICC 10224553
Sign Name	Seth Lynn	Expiration Date	7/7/24
Testing Company	Midwest Tank Testing	Telephone #	800-975-1436
Address	316 W. Indiana Ave.		
City/State/Zip	Chesterton, IN 46304		

	Serial Number	
IN-TANK MICROPHONE	M1904001/M2106004/M1537006	
ACOUSTIC SIGNAL PROCESSOR	E1815004	
PRESSURE SENSOR	40665414 and 40665314	
WATER SENSOR DISPLAY	D1902350 and D1411504	
WATER SENSOR PROBE	P1404102 and P1404106	

Calibration Expiration Date	
November-22	

COMMENTS/RECOMMENDATIONS: Biocide was used with water calibration to test for water intrusion.

