

000
Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) # 2871

Contact Number

Facility Name Cenco

Contact email

Address 104 Lincolnway, Exton, PA

Date of Inspection 09/21/21

Operator on Duty Name

46350

Name of the Person Conducting Inspection AKSHIT

Operator Training current

Operator Training
☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Is Registration current with correct owner, operator etc.

Registration/Notification Form
☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Release Detection Method

Release Detection
☒ ATG ☐ JIM
1 R 7 L 5 3 5 2

☐ SIR

☐ IC ☐ Other

Does it have paper?

Is it in Alarm mode?

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Are Spill Buckets Clean and free from water, debris, product etc?

Spill Buckets
☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Are the Spill Bucket in good condition and free of damage/cracks

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

Fill Ports
☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc?

Piping/STP Sumps
☐ Yes ☒ No

Operator Notified

☒ Yes ☐ No

Are UDCs clean and free from water, debris, product etc?

Under Dispenser Containments (UDC)
☐ Yes ☒ No

Operator Notified

☒ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

317-645-0215

tanksdata@gmail.com

www.tanksdata.com