

30 DAYS WALK THROUGH INSPECTION

001
Tanks Data

UST Facility I.D. (FID) # <u>2871</u>	Contact Number
Facility Name <u>Kenco</u>	Contact email
Address <u>104 Lincolnway, La Bate, IL</u>	Date of Inspection <u>02/16/25</u>
Operator on Duty Name <u>YG350</u>	Name of the Person Conducting Inspection <u>AKSHIT</u>

Operator Training current

Operator Training
☒ Yes ☐ No

Operator Notified ☐ Yes ☐ No

Registration current with correct owner, operator etc.
☐ Yes ☐ No

Operator Notified ☐ Yes ☐ No

Release Detection Method

Release Detection
☒ ATG ☐ CIM ☐ SIR ☐ IC ☐ Other

Make and Model

Does it have paper?

Is it in Alarm mode?

Interstitial Monitoring Sensor Status Normal
 Necessary Monthly Printout Taken

Operator Notified ☒ Yes ☐ No
 Operator Notified ☒ Yes ☐ No
 Operator Notified ☒ Yes ☐ No

Spill Buckets

Are Spill Buckets Clean and free from water, debris, product etc?
 Are the Spill Bucket in good condition and free of damage/cracks

Operator Notified ☒ Yes ☐ No
 Operator Notified ☒ Yes ☐ No
 Operator Notified ☒ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

Operator Notified ☒ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc?

Operator Notified ☒ Yes ☐ No

Are UDCs clean and free from water, debris, product etc?

Operator Notified ☒ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS
 FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

317-645-0215

tanksdata@gmail.com

Signature

Date

www.tanksdata.com