

Work Order: 416037

Status: Invoiced

Date:

6/13/2025

Location: LA PORTE CITGO

Bill To: LA PORTE CITGO

**Prabh
104 E LINCOLNWAY
LA PORTE, IN 46350**

**104 E LINCOLNWAY
LA PORTE, IN 46350**

Solution Notes

[Issue:] replaced spill bucket nipple in regular
Patrick 6/13/25

Installed a new 8 inch nipple in regular spill bucket so that the drop tube flapper is set to 90%. Filled out form and all okay.

Subtotal:

SC/ST:

Total: